intelliGen Ship Loose or Service Parts

Description of Ship loose/Service Part	Part Number	List Price
Transducer Replacement Kit	28911202	$356
Temperature Sensor Kit - White Leads*	89904903	$77
Pressure Transducer Harness	22515102	$246
EXV Replacement Kit		
E2V11BWAE0 - 3/8" x 3/8" Conn	29326101	$1,226
E2V24BWAE0 - 3/8" x 3/8" Conn	29326201	$1,226
E2V24BSMEO – 5/8" X 5/8" Conn	29326401	$1,226
E3V45BSMEO – 7/8" X 1 3/8" Conn	29326501	$2,409
E2V11BWAE0 – 7/8" X 1 3/8" Conn	29326601	$2,409
Expansion Valve molded connector - 40" Conn (Bipolar Valves)	22592101	$222
Transformers		
120/24 volt - 40 VA	22529601	$113
240/24 volt - 40 VA	22529602	$114
460/24 - 40 VA	22529603	$139
600/24 - 40 VA	22529701	$191
iRC Main Control Board Replacement Kit	28918001S	$1,250
iRCUI User Interface Replacement Kit	28918201S	$846
iWC Webserver Card Replacement Kit	28918301S	$1,108
iIC Integration Card Replacement Kit	28918401S	$641
Cable Ribbon. iRC-UI to iRC Center Mount Unit Cooler 8" Replacement Kit	22602101	$157
Cable Ribbon. iRC-UI to iRC - Low Profile Unit Cooler 14" Replacement Kit	22602102	$309
Cable Ribbon. iRC-UI to iRC- Medium Profile and Large Unit Cooler 24" Replacement Kit	22602104	$467
Cable Ribbon. iRC-UI to iRC - Large Unit Cooler 35" Replacement Kit	22602103	$621
EV-COM Cable- Large Unit Cooler DUAL iRC Board Replacement Kit	22596801	$777
Door Switch Kit (includes door switch and 2 ft cable)	22543102	$287

*Only the sensor with white leads is shipped as a service replacement part